

## STRUCTURAL STABILITY CERTIFICATE

1. Inspector Name : Dr.U.Ranga Raju
2. Building Name : VISHNU SCHOOL
3. Building Permit Number : P.R. No: 16 Dt: 31.05.2010
4. Address : VISHNU SCHOOL  
SRI VISHNU EDUCATIONAL SOCIETY  
VISHNUPUR, KOVVADA (Village) , BHIMAVARAM  
West Godavari District, AP
5. Description/ Classification of Building : A.C.C. Sheet roofed (Photos)  
**Dining hall**
6. Owner : SRI VISHNU EDUCATIONAL SOCIETY
7. Period For Which the Certification is issued : 10 Years ( 2020 – 2030) Renewable
8. Nature of defects, if any
- a) Foundation and basement : Nil
- b) Super Structure : Nil
- c) Doors & Windows : Nil
- d) Wood work : Nil
- e) Roof : Nil
- f) Flooring : Nil
- g) Miscellaneous (Cracks, etc.,) : Nil
9. Any major defects noticed which will render the building unsafe in any manner : Not found
10. Whether maintenance works have been done properly : YES
11. Whether the structure is sound or not for Occupancy : Structure is sound for occupancy

## CERTIFICATE

It is certified that the building was inspected by me on 20.03.2020 and found to be fit for human habitation and occupancy, for the period of 10 years (2020-2030) the reason stated above.

Place : Bhimavaram  
Date: 20.02.2020

  
Building Inspection Engineer  
**Dr. U. RANGA RAJU**  
M.E., Ph.D (IITM)  
Licensed Structural Engineer  
BHIMAVARAM MUNICIPALITY